Access Control Terminal K1T801
V2.0.2_build190301 Release Notes

Device Model: DS-K1T801E DS-K1T801M	Firmware Version	V2.0.2_build190301
	4200 Version	V2.6.5.6 build20171016

Reason of Upgrade

Add or modify functions, fix bugs, enhance products quality and meet customers' requirements.

Bugs Fix

1. Fixed open timeout logic error defect after configure door open timeout 255s;

Customer Impact and Recommended Action

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

For questions or concerns, please contact our local technical support team.

> Note:
> - Hikvision has all rights to alter, modify and cancel this notice.
> - Hikvision doesn't give any guarantee for old models' stock.
> - Hikvision is not liable for any typing or printing errors.
> - For special model's change details, please contact our local technical support team.